

# **IMPORTANT SAFETY NOTICE**

## **TenPoint and Wicked Ridge crossbows**

TenPoint has discovered that arrows can release from certain crossbows following a sequence of actions involving: 1. pulling the trigger while the safety is on “safe/white”, 2. moving the safety knob to “fire/red”, 3. unsuccessfully attempting to return the safety knob to “safe/white”, and 4. pulling the trigger a second time believing the safety knob has fully returned to “safe/white”.

TenPoint is voluntarily recalling affected models for repair that fail to pass a self-test.

The affected models include the TenPoint Shadow Ultra-Lite, Turbo XLT II, Titan Xtreme, Maverick HP, GT Flex, and Phantom CLS-S and the Wicked Ridge Warrior HL, Invader HP and Raider CLS crossbows manufactured between 2011 and 2014.



Visit [www.tenpointcrossbows.com](http://www.tenpointcrossbows.com) for a list of affected serial numbers, self-test instructions, and a self-test instructional video to determine if your crossbow requires repair.

Immediately stop using your crossbow if it is within the recall scope until you perform the self-test. If you confirm, through the self-test, that your crossbows is affected, contact TenPoint to have the safety mechanism repaired free of charge.

For further information, please visit [www.tenpointcrossbows.com](http://www.tenpointcrossbows.com), call (800) 548-6837 from 9 a.m. to 5 p.m. ET Monday through Friday or email us at [safetyrecall@tenpointcrossbows.com](mailto:safetyrecall@tenpointcrossbows.com).